



LOCATION: Kansas City, MO OWNER: Missouri DOT CLIENT: Clarkson Construction

- $\checkmark$  Determination of existing bearing forces
- ✓ Design of falsework system and jacking sequence for bearing repairs
- ✓ LiDAR Scanning of project site for falsework height verification

(816) 421-1520 www.genesisstructures.com/contact-us/